



CofC

U.S. Patent No.: 7,128,091

Serial No.

: 10/669,331

Filed

: September 25, 2003

Issued

: October 31, 2006

For

: SEXLESS COUPLING FOR FIRE HYDRANT-FIRE HOSE CONNECTION

## PETITION FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323

Assistant Commissioner for Patents Washington, D. C. 20231

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

## I. C.F.R. § 1.322

The mistake(s) were incurred through the fault of the Patent and Trademark Office and are clearly disclosed in the records of the Office. Therefore, no fee is due.

## II. <u>C.F.R. § 1.323</u>

At least some of the mistakes was/were made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing errors that have been found in the above-identified patent. The error(s) are of a clerical or typographical nature or of minor character and were made in good faith. The requested correction(s) does not constitute new matter or require reexamination.



III. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,

O. Many for JRM

John R. Moses, Reg. No. 24,983

Attorney for Applicants

MILLEN, WHITE, ZELANO & BRANIGAN, P.C.
Arlington Courthouse Plaza I
2200 Clarendon Blvd. Suite 1400
Arlington, Virginia 22201
Telephone: (703) 243-6333

Facsimile: (703) 243-6410

Attorney Docket No.: HYDRA-0036

Date: May 18, 2007

JRM/cht

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,128,091

DATED : October 31, 2006 INVENTOR(S) : Roy Istre

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 17 reads "port" should read -- portion --

Column 7, line 42 reads "fri" should read -- in --

Column 8, line 7 reads "adiacent" should read -- adjacent --

Column 8, line 13 reads "iuncture" should read -- juncture --

MAILING ADDRESS OF SENDER:

Millen, White, Zelano & Branigan, P.C. 2200 Clarendon Blvd, Suite 1400 Arlington, VA 22201 PATENT NO. 7,128,091

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.